

BUILDING SAFETY CERTIFICATE


This is to Certified that I have inspected the building of **Macaroon Students Academy, Bhadrawati, Dist. Chandrapur** at Survey No. **259**, Mouza **Bhadrawati, Dist Chandrapur 442902** and found that building is RCC frame structure having Ground Floor+1 area **3863.773 sq.m.** Building is constructed for school education purpose with sufficient facilities like Laboratory, Sanitation, Sewage Disposal System, Lighting Ventilation, First aid facility, Safe drinking water, Playground, Ramp at Entrance, security system, Fire fighting System and emergency exit etc. The School Building Leased by **Maharashtra Shikshan Prasarak Mandal, Chandrapur**. As per Drawing of building provided by school and stability certificate for school building issued from Structural consultant (Jyoti Associates, Er. Pramod Gurmule, Structural Engineer), the above mentioned owners/occupants have complied with the Building Bye Laws in accordance with rule of State/UT, and incorporate the provisions of building safety as specified in National Building Code 2005, 2016 and as amended thereafter and has been verified by the officer of this office on 22/05/2025 (date of Inspection) in the presence of **Miss. Rajda Siddiqui, Principal Macaroon Students Academy, Bhadrawati** and that the said above building/premises is safe and fit for running School with effect from 02/06/2025 for a period ONE year in accordance with rules.

This certificate is issued on request letter of **Principal, Macaroon Students Academy, Bhadrawati, Dist. Chandrapur** for CBSE board affiliation purpose



Outward Na. 06/1589/2025
Office of the Executive Engg.
P.W. Division, Chandrapur
Date:- 03/06/2025


Sub-Divisional Officer
Sub-Divisional Officer Chandrapur
Counter Sign


Executive Engg.
P.W. Division, Chandrapur (P.W. D.)
जिल्हा परिषद, चंद्रपुर

✓ To,
Macaroon Students' Academy
259, Bhadrawati, Dist. Chandrapur 442902